




Legend


-  Dam Embankments
-  ST-18 Pond Inundation Area

Note:

Because of the methods, procedures, and assumptions used to determine the flooded areas — the limits of flooding shown are approximate and should be used only as a guideline for establishing evacuation zones. Areas inundated in an actual event will depend on actual failure conditions and may differ from areas shown on the maps.



Date: Jun 03 2011 10:57:13 AM User: bhumer
File: F:\Inundation\400 19 00\Design\Civil\GIS\ST_18_Pond_Inundation_Map.mxd



REVISIONS:

**PAPE-DAWSON
ENGINEERS**

555 EAST RAMSEY | SAN ANTONIO, TEXAS 78216 | PHONE: 210.375.9000
FAX: 210.375.5010
TEXAS BOARD OF PROFESSIONAL ENGINEERS, FIRM REGISTRATION #470

**ST-18 Pond
Dam Breach
Inundation Map**

JOB NO. 400-19-00
DATE Jun 2011
DESIGNER JML
CHECKED RH DRAWN JML
SHEET 1